



NOTICE OF AWARD

CARSAN AUTO SERVICE AND TRADING CENTER
 #1 Sitio Ibayo, Sumulong Hi-way Brgy. Mayamot Antipolo City
 Tel No. 8560-7599, 0917-1597-700
 Email address: carsan_auto2@yahoo.com

Attention: Mr. Carlo L. Santos
 Authorized Representative

Dear Mr. Santos:

We are pleased to inform you that your quotation for the procurement of Preventive Maintenance Scheduling of Various Toyota vehicles under QN 2023-010-MAR with the quotation price of **Ninety Nine Thousand Pesos (P 99,000.00)** has been determined to be the single calculated and responsive quotation, to wit:

Item no.	ABC	Qty Unit	Item	Price		Awarded to:
				CARSAN AUTO SERVICE AND TRADING CENTER		
1	22,500.00	1 unit	<p><i>Request for Preventive/Period Maintenance Scheduling of the following units:</i></p> <p>2019 Toyota Hiace with Conduction Number POF293 for 35,000 km PMS</p> <p>With the following scope of work:</p> <ul style="list-style-type: none"> • Engine oil change and decarbonize (intake) • Replace oil, fuel and air filter • Injector cleaning • Clean and adjust brakes • Check air-conditioning system and replace cabin filters • Check suspension and re-tight bolts 	17,000.00	17,000.00	CARSAN AUTO SERVICE AND TRADING CENTER
2	21,000.00	1 unit	<p>2017 Toyota Hiace with Plate No. SAB-4122 for 30,000km PMS</p> <p>With the following scope of work:</p> <ul style="list-style-type: none"> • Engine oil change and decarbonize (intake) • Replace oil, fuel and air filter • Injector cleaning • Clean and adjust brakes • Check air-conditioning system and replace cabin filters • Check suspension and re-tight bolts 	16,500.00	16,500.00	
3	22,500.00	1 unit	<p>2017 Toyota Hiace with Plate No. SAB-4124 for 45,000km PMS</p> <p>With the following scope of work:</p> <ul style="list-style-type: none"> • Engine oil change and decarbonize (intake) • Replace oil, fuel and air filter • Injector cleaning • Clean and adjust brakes • Check air-conditioning system and replace cabin filters • Check suspension and re-tight bolts 	17,000.00	17,000.00	


Item no.	ABC	Qty /Unit	Item	CARSAN AUTO SERVICE AND TRADING CENTER		Awarded to:
4	22,500.00	1 unit	2017 Toyota Hiace with Plate No. SAB-4125 for 30,000km PMS With the following scope of work: <ul style="list-style-type: none"> • Engine oil change and decarbonize (intake) • Replace oil, fuel and air filter • Injector cleaning • Clean and adjust brakes • Check air-conditioning system and replace cabin filters • Check suspension and re-tight bolts 	16,500.00	16,500.00	CARSAN AUTO SERVICE AND TRADING CENTER
5	20,500.00	1 unit	2017 Toyota Hiace with Plate No. SAB-4126 for 70,000km PMS With the following scope of work: <ul style="list-style-type: none"> • Engine oil change and decarbonize (intake) • Replace oil, fuel and air filter • Injector cleaning • Clean and adjust brakes • Check air-conditioning system and replace cabin filters • Check suspension and re-tight bolts 	16,000.00	16,000.00	
6	20,500.00	1 unit	2017 Toyota Hiace with Plate No. SAB-4127 for 50,000km PMS With the following scope of work: <ul style="list-style-type: none"> • Engine oil change and decarbonize (intake) • Replace oil, fuel and air filter • Injector cleaning • Clean and adjust brakes • Check air-conditioning system and replace cabin filters • Check suspension and re-tight bolts 	16,000.00	16,000.00	

A Purchase Order shall be issued at the soonest possible time.


Kindly submit your Bank Account No. pursuant to DBM Circular Letter No. 2018-14 dated 28 December 2018 Re: Updated Guidelines in the Implementation of the Modified Direct Payment Scheme (MDPS) Due Creditors/Payees.

We appreciate your interest in this opportunity and we look forward to the satisfactory performance of your obligations under the project.

Very truly yours,


 WARREN REX H. LIONG
 Overall Deputy Ombudsman - 1-

Date: _____



Received by:
 CARLO L. SANTOS
 (Signature above printed name)

3-27-2023
 (Date and time of receipt)

*Kindly fax email to sender to acknowledge receipt